



Before using emblem removal spray

please read MSDS / instructions for safe use



Step by step guide

Before using emblem removal spray, test for suitability of the fabric as the product can affect certain man-made fibres.

HEAT SEALED EMBLEM / LABELS

Shake	Spray	Wait	Remove
Shake aerosol can before use	On the back of the emblem/label	3-4 seconds	Remove the item by peeling from the edge

Spray emblem removal spray onto the back of the emblem/label through the garment. Allow to penetrate for 3-4 seconds and remove the item by peeling from the edge.

TRANSFERS, VINYL & GARMENT FILMS

Shake	Spray	Wait	Remove
Shake aerosol can before use	On the back of the transfer/film <i>Or if this is not possible spray directly onto the transfer/film</i>	5 seconds <i>Or up to 30 seconds if it needs to penetrate</i>	Remove the remainder of the substance of the fabric

To remove transfers, cad-cut vinyls and garment films: spray the emblem removal spray on the back of through the garment (if this is not working or fabric is too thick spray it directly onto the transfer or film and allow to penetrate and carefully peel away the logo. To aid removal of some types of transfers, it may be necessary to overseal with a patch emblem first and then spray on the back of through the garment and remove the patch emblem including the transfer.

Above step by step guide is the standard recommendation for the removal of the product.

However there are many different factors that can vary to get a good result. The result is very dependent on the type of product, the quality of the adhesive, the pressure that is used in the application and the type of fabric (thickness and treatment).

The product is extremely flammable. Vapours may form explosive mixtures with air. Pressurised container: may burst if heated. Containers can burst violently or explode when heated, due to excessive pressure. Eliminate all sources of ignition. No smoking, sparks, flames or other sources of ignition near spillage. Provide adequate ventilation. Absorb in vermiculite, dry sand or earth and place into containers. Keep away from heat, sparks and open flame. Read and follow manufacturer's recommendations. When sprayed on a naked flame or any incandescent material the aerosol vapours can be ignited. Use suitable respiratory protection if ventilation is inadequate. Protect from freezing and direct sunlight. Store in a dry place. Wear suitable protective equipment for prolonged exposure and/or high concentrations of vapours, spray or mist. Eyewear complying with an approved standard should be worn if a risk assessment indicates eye contact is possible. Vapours in high concentrations are narcotic. Vapours may cause headache, fatigue, dizziness and nausea. Can cause serious eye irritation if not used as recommended. Wash promptly with soap and water if skin becomes contaminated. Do not eat, drink or smoke when using this product. Containers should be thoroughly emptied before disposal because of the risk of an explosion. Do not pierce or burn, even after use.